

GE 230 - Check Sheet

M: 16052

Keys:

Vin# 46121717906615

ODO: 38311

Year: 1991

Condition: 9.0/10

Rust: 9/10 little to none - Hood front ctr from Oil Canning.

Emblems: Hood and mirror emblems missing

Interior Trim: 9/10 Front, 8/10 Rear normal wear

Canvas Top: 8/10 Front, 8/10 Rear tops soft/playable Windows scuffed

Fuel Added:

X

\$13,900

Charging Test:

Voltage (battery/charging):

ELECTRICAL/LIGHTS:

Turn Signals

X

Reverse Lights

X

Headlights Hi/Lo

X

Brake Light

X

Running Lights

X

Dome

X

License Plate Light

X

Blower Motor

X

RUN TEST:

Transmission - All Gears

X

T-Case Lo

X

Transfer Case Hi

X

Rear Locker

X

Operating Temp Good

X

BRAKE TEST:

Normal

X

Needs Work

Comments:

Good starter, engine compartment clean. Tire Carrier NOT cracked.

****Has Newer Style Front Axle that allows Front locker to be installed.

Equipment in Truck:

Fording kit, fuel nozzle, operaors manual, tow strap, grease gun, tire gauge,

bucket brush

Deficiencies:

Slight bend in drive door edge above door handle, dent RT RR bumper RT of hitch

brake reservior overfilled. Small dent by driver door mirror by window.

Inspector Mason